

Conditions of Installation

1. Where Installation is part of the quotation - To ensure that our customers receive the best product, the best installation and so the best final result, we at Infinity Seating Solutions require that the following conditions are met prior to the installation of Infinity Seating Solutions products. We will contact you well before installation to ensure that the above requirements are being met. We will then also carry out a final survey prior to installation.
2. Access - Direct motor vehicle access to the site and uninhibited and uninterrupted access to the appropriate room(s) is required. The room(s) must be free of hindrances that could obstruct the installation work (i.e. scaffolding). Additionally, it is required that electricity and proper lighting are available. If the building is equipped with a lift, it too must be available to the fitters.
3. Floor Surface - Regardless of the floor type, the floor surface must be free of any irregularities that could obstruct proper installation of the seating. Additionally, any degree of incline must correspond to our agreed specifications.
4. Fixing to the Floor - In order to determine the type of fixings required, we must be informed of the type of flooring present (concrete, plywood, carpet etc) also the floor must be capable of 'holding' the fixings—this is of particular concern with wood flooring. The said flooring must be completed prior to the seating installation with any necessary tests carried out. Plywood flooring is to consist of two 18mm sheets cross laid. We are not responsible for any problems arising from the fixings due to an unsuitable floor, sub-floor or floor-covering.
5. Handover - Should further construction or installation work follow the installation of Infinity Seating Solutions products, the condition of the seating must be evaluated and recorded immediately by a qualified person prior to that works commencement.

Note: Infinity Seating Solutions reserves the right to invoice the customer for any additional costs incurred due to any absence of the above requirements.